
### **REPORT**

### **CPT2760**

Prepared for: Han-Cock Trading and Projects

Attention: Andrew Enslin



Centre for Polymer Technology (Pty) Ltd.

Reg No: 2006/012857/07

Postnet Suite # 186, Private Bag X025, Lynnwood Ridge 0040 Building 14A, CSIR Campus, Meiring Naude Rd, Brummeria

Telephone: 012 841 2618 • Facsimile: 012 349 1710 Email: info@cpttech.co.za · http://www.cpttech.co.za

Directors: Liza Van Eeden (Financial Director), Bernard Reeksting (Technical Director) Reg No.: 2006/012857/07 VAT No.: 488 022 8178

DATE: 02/12/2013 Page 2 of 7 REF CPT2760 ISSUE No: 1

# **CONTROL DOCUMENT**

DEGREE OF CONFIDENTIALITY	Confidential			
TERMS AND CONDITIONS (Please refer to the full set of terms and conditions as recorded on the quotation sheet)	1. The results of this project and / or the CPT staff are not available for any legal proceedings unless thus arranged prior to the contracting of this project.  2. The results and conclusions of the report/test certificate are made to the highest standards, however the Centre for Polymer Technology (Pty) Ltd cannot be held liable for any losses or damages that may result from the use of the contents of the report.  3. If published or reproduced by a client, a test report/test certificate shall be reproduced in full; CPT reports/test certificates may not be reproduced in part.			
TITLE	UV testing of materials exposed to sunlight SANS 151			
AUTHOR	NAME SIGNATURE			
	S. Botha	- Commence		
	DATE	02/12/2013		
DATE OF ISSUE	02/12/2013			
NUMBER OF PAGES	7			
ISSUING ORGANISATION				
Centre for Polymer Technology (Pty) Ltd Postnet Suite #186 Private Bag x025	Telephone: (Nat) (012) 841 4969 (Int) +27 12 841 4969			
Lynnwood Ridge 0040	Telefax: (Nat) (012) 349 1710 (Int) +27 12 349 1710			
CONTRACT NAME	S4239			
PROJECT NUMBER	CPT2760			
ISSUE NUMBER	1			
COPY NUMBER	1			
APPROVED BY				
RESPONSIBILITY	NAME	SIGNATURE		
Technical Director	O. B. Reeksting	OBRELITY		
DISTRIBUTION				
COMPANY	REPRESENTATIVE	COPY NUMBER		
Han-Cock Trading and Projects	Andrew Enslin	1		
CPT	Liza van Eeden	2		

# CONTENTS

INTRODUCTION	4
SAMPLE INSPECTION	4
TESTS CONDUCTED	4
METHOD OF TEST	4
RESULTS	6
DISCUSSION OF RESULTS	6
ANNEXURE	7

DATE: 02/12/2013 Page 4 of 7 REF CPT2760 ISSUE No: 1

### INTRODUCTION

Centre for Polymer Technology (Pty) Ltd were approached by Andrew Enslin from Han-Cock Trading and Projects to test the LNB Protector which is exposed to sunlight.

### **SAMPLE INSPECTION**



Figure 1 – LNB Protector

### **TESTS CONDUCTED**

Impact at 23°C before and after UV weathering UV stability of part (ASTM G154)

#### **METHOD OF TEST**

#### **Impact Resistance**

A steel rod striker with a 6.5mm radius tip was used to impact the sample before and after UV exposure at 23°C. The impact energy was 7.5Joule and the energy was calculated by multiplying the height of the fall (in meters) and the weight (in kilograms) of the striker used.

DATE: 02/12/2013 Page 5 of 7 REF CPT2760 ISSUE No: 1

# UV durability ASTM G154

Test specimens were mounted with the test surface facing the UV lamps. QUV equipment was used to conduct testing for 240 hours using a cycle of 4hour UV exposure at 60°C and 4hour condensation exposure at 50°C.

DATE: 02/12/2013 Page 6 of 7 REF CPT2760 ISSUE No: 1

# **RESULTS**

# Impact Resistance

SAMPLE	TEST METHOD	RESULT
Before UV aging	7.5J impact was performed on the outer tank at room temperature. Impact was performed before and after UV aging of 240hours. The	no surface cracks nor breaking of part
After UV aging	samples were evaluated for cracks and surface damage	no surface cracks nor breaking of part

# **UV Stability**

SAMPLE	TEST METHOD	RESULT
LNB Protector	ASTM G154 for 240hours.	No colour changes, or dimensional changes (shrinkage) occurred after the accelerated weathering.

# **DISCUSSION OF RESULTS**

UV weathering the part under the conditions of ASTM G154 at 240 hours did not show any signs of discolouration, breaking or cracking when impacted. Refer to figures 2 and 3.

.

DATE: 02/12/2013 Page 7 of 7 REF CPT2760 ISSUE No: 1

# **ANNEXURE**



Figure 2 – Visual appearance before and after UV




Figure 3 – Dimensions before and after UV